

- 1. ADEQUATE STRUCTURAL SUPPORTS AND THE NUMBER AND TYPE OF FASTENERS REQUIRED TO COMPLY WITH ACCEPTABLE CODES, SHOULD BE DETERMINED AND VERIFIED BY PROJECT ARCHITECT/ENGINEER.
- 2. ADDITIONAL 80 MILS OF HYDROGEL IS REQUIRED OVER BOARD JOINTS WITHOUT JOIST OR SOLID BRIDGING SUPPORT (SEE INSET DETAIL)



DRAWING NO.: HYD-3.07v1

SCALE: NOT TO SCALE

EFFECTIVE DATE:.